Ford

Technical and Transportation Services Manufacturing Operations



0965

Ford Motor Company 3001 Miller Road Dearborn, Michigan 48121

September 22, 1989

Asbestos Coordinator Air Enforcement U.S. E.P.A., Region V 230 S. Dearborn Street Chicago, Illinois 60604

Subject:

Notification of Intent to Remove Asbestos During Renovation

Attached please find necessary information regarding our intent to remove asbestos during renovation of the Transportation Services Building at the Ford Motor Company Rouge Complex.

If you have any questions or require further information, please contact me at (313)594-1014.

W. B. Dotterrer

Copy to:

Asbestos Coordinator Air Quality Division

Michigan Department of Natural Resources

P.O. Box 30028

Lansing, Michigan 48909

Wayne County Health Department Air Pollution Control Division

2211 East Jefferson Detroit, MI 48207

0681-JM

ml 30/ 90

## NOTICE OF INTENT

Facility Location/Owner: Ford Motor Company

Transportation Services Building

3001 Miller Rd.

Dearborn, Michigan 48121

Description of Facility: The Transportation Services Building houses

administrative offices and a truck repair/service garage for the transportation activity of the

Rouge Complex.

Size of Facility:

120.000 sq.ft.

Age of Facility:

Constructed in 1942

Estimate of the Approximate Amount of Friable Asbestos Material:

300 linear feet

Starting Date: So

September 23, 1989

Ending Date:

September 24, 1989

Nature of Renovation: The renovation involves removing damaged thermal

insulation containing asbestos. Damaged straight pipe and pipe fitting insulation will be removed from the first floor mechanical room, the water tank in the balcony, the shop area and the fan units on the second

floor.

Procedures to be Used: Removal of the damaged asbestos containing materials

will be accomplished using modified negative pressure

enclosure and glove bag techniques. Clean air

monitoring will be completed in accordance with OSHA Standard 29 CFR 1926.58. Air samples of the areas will be taken before the abatement project begins. Personal and work area air samples will be taken during removal operations. And, at the end of the project, air samples will be taken to determine if the

areas are clean.

Name and Location of Disposal Site: The asbestos containing insulation will be disposed at:

Wayne Disposal. Inc. 49350 North Service Drive Belleville, MI 48128